

Modeling and Casting Studios, 3D Studio Safety plan

Safety can only be achieved through teamwork at Modeling and Casting Studios. Each employee, instructor, and student must practice safety awareness by thinking defensively, anticipating unsafe situations and reporting unsafe conditions immediately.

1. Modeling and Casting Studios(FA215C, FA215D, FA215F) and 3D studio (FA215A) are **24 hours** access studios. Monitor will be available during the hours posted in the studio.
2. All students have the responsibility to keep these studios a dust free environment. Scrape materials including clay, plaster, wax etc. should be picked up immediately. The studios should be cleaned up daily.
3. Ventilation must be used when working with resins, wax, plaster etc. Wear protective gloves, goggles, apron, and dust mask.
4. Safety procedures is clearly defined and posted. All instructors who willing to use the Casting Studios for their class must identify required training process with instructions in the syllabi, and **make sure training happens.**
5. All instructors have the responsibilities to make sure the studio is clean after each assigned duty day, and make sure students spend the last 10 minutes of each day cleaning up their own mess and the common area. All tools, equipment used must be return to their proper place. Report anything that needs repair or replacement to the department.